

LOAD/UNLOAD OPERATION CONTROL METHOD . . . irano et al. reer, Burns & Crain, Ltd. (Patrick Burns) Ref. No. 0941.65876 Sheet 1 of 20 (312) 360 0080











FIG.3






FIG.4






FIG.5



LOAD/UNLOAD OPERATION CONTROL METHOD . . . Hirano et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65876
Sheet 5 of 20 (312) 360 0080

FIG.6






FIG.7







FIG.8



LOAD/UNLOAD OPERATION CONTROL METHOD Hirano et al. Greer, Burns & Crain, Ltd. (Patrick Ref. No. 0941.65876 Sheet 7 of 20 (312) 360 0080





-1G. 9





LOAD/UNLOAD OPERATION CONTROL METHOD Hirano et al. Greer, Burns & Crain, Ltd. (Patrick Ref. No. 0941.65876 Sheet 9 of 20 (312) 360 0080


FIG. 11


















LOAD/UNLOAD OPERATION CONTROL METHOD Hirano et al. Greer, Burns & Crain, Ltd. (Patrick B Ref. No. 0941.65876 Sheet 14 of 20 (312) 360 0080



LOAD/UNLOAD OPERATION CONTROL METHOD Hirano et al.
Greer, Burns & Crain, Ltd. (Patrick B Ref. No. 0941.65876
Sheet 15 of 20 (312) 360 0080









FIG.18




DOOMEDIE LOOPYOL







TIME (ms)



LOAD/UNLOAD OPERATION CONTROL METHOD . . . Hirano et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65876
Sheet 20 of 20 (312) 360 0080



▼ TIME (ms)

